

Soldering Hearth

- Material: metal (not aluminium)
- Wear face shield and leather gloves
- If you burn yourself then run it under the cold tap for 10 minutes.
Seek first aid and medical aid
- Hold hot work with tongs
- Leave torch unattended with a yellow flame