

Enamelling Kiln

- Materials: lead free enamelling metals
- Wear safety spectacles and long gloves
- Keep enamelling kiln on fire proof base
- Use firing fork and firing mesh
- If you burn yourself then run it under the cold tap for 10 minutes
Seek first aid and medical aid